

BP GoM Multi-Field Riserless Intervention Campaign – Mechanical and Hydraulic

OWI MED September 20, 2022

Matthew Vick BP Senior Subsea Wells Engineer



Agenda

- 1. Field Overviews
- 2. Intervention SoW
- 3. Intervention Equipment Philosophy
- 4. Planning and Assurance
- 5. Execution
- 6. Intervention Performance
- 7. Lessons Learnt and Best Practices
- 8. Q&A



Field Overviews

Field A

- •28 wells (producers and injectors)•First oil 2008•Water depths 5,600 to 6,300 ft
- •5" 15k Subsea VXTs
- •Completions cased and perforated, frac pack, DHFC

•Intervention scopes

- Stimulation
- Xylene soak
- Sand consolidation
- Scale squeeze
- Production logging
- Water shutoff
- Slot cutting

Field B

- •30 wells (producers and injectors)•First oil 2007•Water depths 4,700 to 7000 ft
- •5" 10k Subsea HXTs
- •Completions frac pack, DHFC

•Intervention scopes

- Crown plugs
- Tubing Drift
- Xylene soak
- Stimulation
- Scale squeeze
- Sand consolidation

Field C

- •27 wells (producers)
- •First oil 2003
- •Water depths 5,400 to 6,900 ft
- •4" 10k Subsea VXTs
- •5" 10k Subsea HXTs
- •5" 15k Subsea HXTs
- •Completions frac pack, open hole gravel pack, DHFC
- •Intervention scopes
 - Crown plugs
 - Well integrity repair
 - Xylene soak
 - Stimulation
 - SCSSV lockout



Intervention Equipment Philosophy


Single supplier contracted to provide vessel, intervention systems, fluid handling equipment, and wireline equipment as a vendor-led solution, with four different intervention technologies used in single campaign

- 1. Mechanical wireline intervention system (also capable of hydraulic stimulation)
- 2. Hydraulic intervention via TRT
- 3. Hydraulic intervention via MARS choke insert
- 4. Well service jumper (offset well access)






Intervention Setup - Mechanical



bp



Mechanica **Deck Layout -**

Intervention Setup Hydraulic (TRT)

DEADMAN TAUT LINE RST OTY 2 x 2" 15K HOSE JUMPER trt Adapter TRT ХT THS

QTY 2 x CT DOWNLINE

QTY 2 x 15K MLWL








Intervention Setup Hydraulic (MARS)

QTY 2 x COIL TUBING DOWNLINES

QTY 2 x 2" 15K MIDLINE WEAK LINKS



WELL TO BE STIMULATED

RST PARKING LOCATION

Intervention Setup – Well Service Jumper





Image courtesy of Caltex

SEAFLOOR

bp

Seafloor Layout – Well Service Jumper





Planning and Assurance






Deploying mechanical well control package

- Integrated project team with expertise in wells operations, interventions, subsea, BOPs, rig systems, marine/vessel, production operations and reservoir engineering
- Strong collaboration between suppliers to deliver integrated intervention systems
- Leveraged lessons learned from previous GoM, North Sea, and West Africa LWIV campaigns


bp


Planning and Assurance

- Developed bespoke intake process for LWIV vessels and well control equipment
 - Existing MODU intake process not fit for purpose
- Risk assessment and management
 - HAZID, HAZOP, FMECA and operational risk assessments completed with full supplier involvement
 - Formal tracking and closeout of all risk actions prior to execution
- Intervention equipment assurance
 - ESD/EQD philosophy and equipment testing
 - Third party verification and regulatory engagement
 - Full scale SIT of well control equipment
- BP rig verification process
 - Marine systems
 - Well control equipment
- Operability analysis, weak point assessment and fatigue management to develop weather windows and watch circles



Onshore SIT of mechanical well control package







Lesson Learned – Stuck Wire (Asphaltenes)

- Slickline became stuck in the pressure control head due to asphaltene build up on the wire during a deep drift run
- Circulated xylene into lubricator below pressure control head to help dissolve asphaltene blockage
 - Successfully remediated and POOH
 - Required full redress of well control package rubbers (ram and PCH) after well due to material compatibility issues
 - Collapsed circulation hose due to subambient conditions
- Lengthened xylene soaks and flowback to start interventions on at-risk wells



Asphaltenes deposited on slickline

Lessons Learnt – Hose Collapse





Collapsed circulation flying lead

High collapse flexible pipe connected to stim




- Collapsed coil tubing hose jumpers (two wells) due to low wellbore pressure while bullheading stimulations
 - No leaks or loss of containment during operations
- Collapsed circulation flying lead (one well) when circulating xylene to remediate stuck wire
 - Multiple pinhole leaks found subsea when pressuring up after xylene soak
- High collapse flexible pipe successfully implemented as hose jumpers for stimulations on lower pressure wells
 - Alternative HCR hose jumpers also being developed



Lessons Learned – Operability Windows

- Inadvertent EQD when UTA fell off mudmat due to high subsea currents (>0.5 knots at seafloor), resulting in WCP emergency shut-in
 - No wire in hole
 - UTA impacted PLET (no damage)
- Revisited operability analysis to refine safe operating windows
- Redesigned UTA and mudmat
 - Larger footprint to reduce tipping risk
 - Developed autoshear functionality (shear pin and guillotine) to leave UTA on mudmat and sever umbilical in event of loss of vessel position







Image courtesy of JDR




- While RIH with slickline, loss of grease occurred with visible ٠ discharge of hydrate \rightarrow grease seal reestablished
- Wire became stuck after RIH additional ~500'
- Wire stuck for ~6 days before hydrate could be disassociated by combination of pulling vacuum and spotting MeOH with $ROV \rightarrow POOH$ with wire
- Lessons learned:
 - PCH chem injection lines were not flushed prior to RIH (seawater trapped) → well entry procedures revised to flush chemical lines with control fluid on every wireline run
 - Seawater slug left in PCH due to flushing method \rightarrow flushing sequence revised to push seawater out top of PCH before effecting wireline seal
 - ROV unable to pull vacuum on upper chem line \rightarrow PCH replumbed to allow ROV access to both chem lines



Lesson Learned – Packoff Failure

- While RIH with R-Lock on slickline, diesel was observed leaking past the upper packoff on PCH.
- Unable to regain seal on upper packoff, emergency packoffs engaged to stop leak and POOH
- Packoffs inspected on deck with visual wear/damage, replaced
- Re-ran R-lock, no leaks, packoffs inspected after run also showed damage/wear
- Finished well utilizing grease/flowtubes to provide seal on slickline as well as packoffs, no further packoff damage seen
- Findings:
 - Grease appeared to lubricate packoff rubbers reducing wear due to diesel
 - Excessive packoff pressure being applied



Packoff damage when RIH with diesel in bore




No packoff damage seen when also using grease with diesel in bore



Lesson Learned – Loss of Grease Seal



Dynamic testing of PCH with wireline



- While RIH and POOH during production logging operations on high pressure well (~9,000 psi SITP), experienced multiple losses of grease seal
- Performed investigation with contributing causes determined:
 - Insufficient grease supply
 - Grease contamination
 - Unreliable grease regulators
- Revised PCH and surface grease supply system between wells:
 - New grease regulators
 - Revised flowtube/injection stackup
 - Additional check valves, gauges, flow meters
 - Performed full scale dynamic testing to qualify new grease control system



Additional Lessons Learned / Improvements

- Delivery of 740 bbls tanks for increased fluid loadout
- Pull wire out of cable head and drop toolstring
- Improvements running/retrieving chokes for MARS interventions
- Stim tool compensation during running to prevent seawater ingress
- Collapsed hose carousels due to hose shrinkage under pressure
- Vessel to vessel fluid transfers
- Transformation of a construction vessel into an intervention vessel




740 bbls tanks being installed

High collapse flexible pipe deployment





Collapsed carousels





MARS insert and running tool in XT



ROV handling of high collapse flexible pipe

Q&A



